UTAH STATE CAPITOL ARCHITECTURE: EXTERIOR SURVEY REPORT

ELEVATION LOCATION: ATTIC

Survey Date: 6/5/00

Code: <u>EX-000</u>

Description: Intrusive Element

Location: House of Representatives

Grid:

Condition: NO

Non-original, incompatible but

essential elements

Comments: flourescent lights block any natural

light; not all are necessary for

sufficient light



Code: EX-022

Description: Skylight roof

Location:

Grid:

Condition: GL

Glass cracked, broken or non-

matching

Comments:



Code: <u>EX-112</u>

Description: steel skylight beam

Location:

Grid:

Condition: MT

Metal damage

Comments: water leaking and damaged frames



Code: EX-113

Description: steel ceiling bracing

Location: Supreme Court

Grid:

Condition: BT

bent, damaged, or failed steel

Comments: bent bracing



ELEVATION LOCATION: ATTIC

Survey Date: 6/5/00

Code: EX-113

Description: steel ceiling bracing

Location: Supreme Court

Grid:

Condition: BT

bent, damaged, or failed steel

Comments: rods hung with wire from beams

causing torsion



Code: EX-114

Description: concrete beam Location: Supreme Court

Grid:

Condition: BR

Broken, severely cracked or

chipped

Comments: serious fractures along an E/W

direction



Code: EX-114

Description: concrete beam

Location: Supreme Court

Grid:

Condition: CR, BR

Cracked and broken element

Comments: serious fractures along an E/W

direction



Code: EX-114

Description: concrete beam

Location: Supreme Court

Grid:

Condition: CR

Cracked element

Comments: serious fractures along an E/W

direction



ELEVATION LOCATION: ATTIC

Survey Date: 6/5/00

Code: EX-115

Description: interior skylight

Location: Supreme Court

Grid:

Condition: INT

Intrusive, non-original, non-

essential element

Comments: incandescent lights may be

original; wiring is sporadic and

unkempt



Code: EX-115

Description: interior skylight

Location: Supreme Court

Grid:

Condition: C

General Cleaning Needed

Comments: this skylight no longer in use:

covered with insulation. 24

9"x12" panes



Code: **EX-115**

Description: interior skylight

Location: House of Representatives

Grid:

Condition: GL

Glass cracked, broken or non-

matching

Comments: unmatched glass



Code: <u>EX-115</u>

Description: interior skylight

Location: Supreme Court

Grid:

Condition: GL

Glass cracked, broken or non-

matching

Comments: plastic glass substitute



ELEVATION LOCATION: ATTIC

Survey Date: 6/5/00

Code: <u>EX-115</u>

Description: interior skylight

Location: Atrium

Grid:

Condition: GL

Glass cracked, broken or non-

matching

Comments: glass not braced

